


1. MECHANICAL & ASSEMBLY :



Before core and case assembling, need to use one drop KE-45W inside the case to fix the core

UNIT:m/m

2. WINDING CONFIGURATION:

STEP	WINDING	MARGIN TAPE	START-FINISH	COPPER WIRE	TURN	LAYER TAPE	TUBE
1	N1	~	1 - 2	0.6 φ	15Ts		
2	N2	~	4 - 3	0.6 φ	15Ts		

REPORT BY	CHECK BY	APPROVED BY	CUSTOMER :	DATE
			PART NO : 50F-17001	REV NO.
			ISSUE NO :	PAGE 2 - 1